

03500.017659

PATENT

COFC
SAY



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

JUNICHI SEKIYAMA ET AL.

Appl. No.: 10/684,468

Filed: October 15, 2003

For: SHEET POST-PROCESSING DEVICE AND)
IMAGE FORMING APPARATUS HAVING
THE DEVICE

U.S. Patent No.: 6,912,044 B2

Issued: June 28, 2005

) : Examiner: Henry H. Nguyen
): Group Art Unit: 2851
): Confirmation No.: 4699
):
):
): Certificate
): SEP 22 2005
): of Correction
): September 16, 2005

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

SEP 22 2005

09/19/2005 ERYALEW1 00000040 6912044
01 FC:1811

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Lawrence A. Stahl
Attorney for Patentees
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,912,044 B2

DATED : June 28, 2005

INVENTOR(S) : JUNICHI SEKIYAMA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 55, "let" should read --lets--.

COLUMN 3:

Line 64, "position" should read --positions--.

COLUMN 8:

Line 9, "10A." should read --100A--.

COLUMN 10:

Line 35, "angle a." should read --angle α --.

COLUMN 11:

Line 23, "slid" should read --slide--.

Line 66, "guides" should read --guides to--.

COLUMN 13:

Line 64, "a side" should read --a part of the slide guide 302 that is on the upstream side--.

COLUMN 14:

Line 43, "301 and" should read --301 and 302--.

COLUMN 15:

Line 21, "rotated" should read --rotated in--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,912,044 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)

SEP 22 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,912,044 B2

DATED : June 28, 2005

INVENTOR(S) : JUNICHI SEKIYAMA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20:

Line 25, 'punched" should read --punched with--.

Line 29, "positions" should read --position--.

Line 56, "by" should read --for--.

Line 61, "way" should read --away--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,912,044 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)



SEP 22 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,912,044 B2

DATED : June 28, 2005

INVENTOR(S) : JUNICHI SEKIYAMA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 55, "let" should read --lets--.

COLUMN 3:

Line 64, "position" should read --positions--.

COLUMN 8:

Line 9, "10A." should read --100A--.

COLUMN 10:

Line 35, "angle a." should read --angle α --.

COLUMN 11:

Line 23, "slid" should read --slide--.

Line 66, "guides" should read --guides to--.

COLUMN 13:

Line 64, "a side" should read --a part of the slide guide 302 that is on the upstream side--.

COLUMN 14:

Line 43, "301 and" should read --301 and 302--.

COLUMN 15:

Line 21, "rotated" should read --rotated in--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,912,044 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,912,044 B2

DATED : June 28, 2005

INVENTOR(S) : JUNICHI SEKIYAMA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20:

Line 25, "punched" should read --punched with--.

Line 29, "positions" should read --position--.

Line 56, "by" should read --for--.

Line 61, "way" should read --away--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,912,044 B2

No. of add'l. copies
@ 30¢ per page